

TEST REPORT

1. PVC (VINYL) FLOOR

TEST RESULTS				
TEST ITEM	UNIT	SAMPLE	RESULT	TEST METHOD
APPERANCE	-	-	NO DEFECTS	KS M 3802 : 2019
LENGTH	MM	-	469.92	KS M 3802 : 2019
WIDTH	MM	-	469.93	KS M 3802 : 2019
THICKNESS	MM	-	3.11	KS M 3802 : 2019
VERTICALITY	MM	-	0.05	KS M 3802 : 2019
INDENTATION (20℃)	MM	-	0.42	KS M 3802 : 2019
INDENTATION (40℃)	MM	-	0.5	KS M 3802 : 2019
RESIDUAL INDENTATION	%	-	3.1	KS M 3802 : 2019
DIMENSIONAL STABILITY BY HEATING (T.D)	%	-	0.08	KS M 3802 : 2019
DIMENSIONAL STABILITY BY HEATING (M.D)	%	-	0.07	KS M 3802 : 2019
WEIGHT LOSS ON HEATING	%	-	0.12	KS M 3802 : 2019
SCRATCH (95% ETHANOL)	MM	-	2.6	KS M 3802 : 2019
SCRATCH (2% NaOH)	MM	-	2.1	KS M 3802 : 2019
SCRATCH (SOYBEAN OIL)	MM	-	2.1	KS M 3802 : 2019
SCRATCH (KEROSENE)	MM	-	2.1	KS M 3802 : 2019
CONTAMINATION RESISTANCE (SOYBEAN OIL)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (LUBRICANT OIL)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (ETHYL ALCOHOL)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (CEMENT PASTE)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (10% AMMONIUM WATER)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (MILK)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (ACETIC ACID)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (5% HCI)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (KEROSENE)	-	-	NO DEFECTS	KS M 3802 : 2019
CONTAMINATION RESISTANCE (SOY SAUCE)	-	-	NO DEFECTS	KS M 3802 : 2019

Shaoxing Wellmark Leather co.,LTD.
Shaoxing Wellmark Textile co.,LTD.